

# **CSMP:** #1 Bright and Shiny [Barley]

## Copper - Level 1

#1 Bright and Shiny [Barley]

## Description

■ #1 bright and shiny copper is clean copper wire with individual strands of 16 gauge or thicker. This material is usually upgraded when insulation is removed from ICW by way of a wire stripper. Something to be aware of is copper-coated steel wire as it looks just like Barely. Testing this material with a magnet can potentially save thousands of dollars.

### Upgrade potential

■ This material is at the top of the copper price range, so there are no upgrades to be recognized. However, on the flip side, there can be no oxidized copper whatsoever within a #1 Bright and Shiny [Barley] package; this would end in a claim or downgrade.

#### ISRI definition

- Barley No. 1 Copper Wire
  - Shall consist of No. 1 bare, uncoated, unalloyed copper wire, commonly known as Bare Bright copper wire. Wire gauge subject to agreement between buyer and seller. Green copper wire and hydraulically compacted material to be subject to agreement between buyer and seller.





